Dec. 1973	Form Approved.
Drawnten States W.M - CARLSBAP	Budget Bureau No. 42-R1424 5. LEASE
10 1985 DEPARTMENT OF THE INTERIOR	LC 054205
D. C. D. GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SIA, OFFICE	And the same of th
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas	West Red Lake Unit
well LA well Cl other	9. WELL NO.
2. NAME OF OPERATOR ARCO Oil and Gas Company	21
Division of Atlantic Richfield Company 3. ADDRESS OF OPERAYOR	10. FIELD OR WILDCAT NAME
P. O. Box 1710, Hobbs, New Mexico 88240	Red Lake Grayburg SA 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA
below.)	3-18S-27E
AT SURFACE: 990' FNL & 2310' FEL (Unit B)	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: as above AT TOTAL DEPTH: as above	Eddy N.M.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14 API NO.
REPORT, OR OTHER DATA	18 ELEVATIONS (CHOW DE LOS AND ME)
, and the second	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3400 DF
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	The state of the s
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING [] [] MULTIPLE COMPLETE [] []	change on Form 9-330.)
CHANGE ZONES	
ABANDON* □	
(other)	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dir measured and true vertical depths for all markers and zones pertinent 	rectionally drilled give subsurface locations and
Propose to P&A in the following manner: MIRU,	inst BOP. POH w/tbg. RIH w/bit
to PBD 1898' RIH w/tbg OE, spot C1 H cmt PRD	1898-1720 WOC. Tag TOC. Circ
well w/9.5 ppg BW cont'g 25# gel/bbl Per 4	2" @ 450'. Set cmt retr @ 400'.
Estab injection rate, squeeze w/Cl H cmt, amt	to be determined by pump-in rate.
Dump 5 sx on cmt retr. Spot 10 sx 9 surf. Cu marker. Clean & level location for abandonmen	
marker. Clean & level location for abandonmen 100 100 (show) and 100	1200
1/100 196 (shore) and 100	1800
1990	1400
0.0	
Pof forth strings-Circle	
1st wow services of	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. Thereby certify that the foregoing is true and correct	
	77.97.795
SIGNED Sich Stuckeller TITLE Engry Tech. Sp	Dec. DATE 7/24/85