

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

1301 W. C. and Avenue
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

C15F

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BP America Production Company

3. Address and Telephone No.

P.O. Box 1089, Eunice, NM 88231

505-394-1649

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter A, 667.12' FNL & 666.05' FEL
Section 1, T18S, R27E

5. Lease Designation and Serial No.

6. If Unit or CA, Agreement Designation

EMPIRE ABO UNIT
NM-70945

7. If Unit or CA, Agreement Designation
8910138010

8. Well Name and No.
Empire Abo Unit "I" 20

9. API Well No.
30-015-01215

10. Field and Pool, or exploratory Area
Empire Abo

11. County or Parish, State
Eddy NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other Workover
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD: 6118' PBD: 6081' PERFS: 5783-6020' (new), 6026-6064' (old)

03.22.02: MIRUPU. NDWH. NUBOP. POH w/rods & tbq.

03.25.02: RIH w/bit, 4-1/2" csg scraper, & tbq. Test tbq in hole. Tag @ 6073'.
POH w/tbg & tools.

03.27.02: RU wireline & perf 5783-5788', 5844-5850', 5866-5869', 5923-5934', 5965-5998', 6002-6013', 6016-6020'. RDWL. RIH w/4-1/2" RBP, pkr, SN, & tbq. Set RBP @ 6025'. Pkr set @ 6015'.

03.28.02: Spot 100 gals 15% HCL acid across perfs. Pull up & set pkr @ 5695'. Pmp'd 2500 gals 15% HCL using 200 1.1 ball sealers. RD pmp truck, unset pkr. RIH, latch on RBP unset & POH. RIH w/192 jts 2-3/8" tbq & SN. Tbg set @ 6030'. SN set @ 6034'.

03/29-04/05: Swab well. NDBOP. NUWH. RDPU. Returned well to production. In 24 hours well produced 4 b0, 6 bw, 144 mcf.

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Sr. Administrative Assistant

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

