

dst
dp

RICT I
Box 1980, Hobbs, NM 88240
RICT II
Drawer DD, Artesia, NM 88210
RICT III
Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAR 19 1991

O. C. D.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator Kersey & Company

Address of Operator 808 Grand, Artesia, N. Mex, 88210

Well Location
Unit Letter J : 2310 Feet From The South Line and 1650 Feet From The East Line

Section 20 Township 17S Range 28E NMPM County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
PORARILY ABANDON ☐ CHANGE PLANS ☐
L OR ALTER CASING ☐
ER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Place Cement plug 1860 - 1960: Need plug 8 7/8" shoe @ 1645 50' in and out
2. Perforate 7" casing at ~~1000~~ 1175 (Queen)
3. Spot 100 cement plug in and out of Casing
4. Perforate 7" casing at ~~500~~ 475' (shoe of 8 1/4)
5. 100' Plug in and out of Casing
6. Surface plug and Marker - 50' cement plug at surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Harold Kersey TITLE Co-owner DATE Mar. 14, 1991

TYPE OR PRINT NAME

(This space for State Use)

APPROVED BY Danell Moore TITLE Geologist DATE 4/5/91

CONDITIONS OF APPROVAL, IF ANY: