

Boyd Operating Co. State C #5-B-14-18-28

8 3/8" - 325-1005X

7" - 2424-150 SX est TOC 625

TD 2588 PB 2544

Comp. O/H - 2424 - 2544 2-7-53

Connected to Lrg. 4-30-62

2 3/8" x 7" Baker shorty Junction Pkr. approx 2251

ran free point found pkr tubing stuck @ 2228, 2218, 2209

Partly stuck @ 2196 tubing free @ 2190 back 7/8" @ 2192

2nd joint above pkr tubing left in hole from 2545 to 2251

10 ft. of tail pipe 7" x 2 3/8" shorty Junction Baker pkr. 2248-51

2 fts. tbg above pkr. Tubing collar looking up @ 2192'

ran new pkr + 71 fts. tbg set pkr @ 2093

went back to lrg. @ 120 BPD @ 1650"