

NO. OF COPIES RECEIVED	
DISTRIBUTION	3
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1287
7. Unit Agreement Name
8. Farm or Lease Name Sheldon
9. Well No. 1
10. Field and Pool, or Wildcat Artesia
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator KERSEY & COMPANY
3. Address of Operator P. O. Box 316, Artesia, New Mexico 88210
4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 13S RANGE 28E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Will set Bridging plug @ ²³⁰⁰~~2200~~' and place 5 sack cement plug on it.
- Plan to put 25 sack cement plug in and out of 5 1/2" casing where cut off.
- Plan to put 25 sack plug in and out of shoe of 8 5/8" casing.
- Plan to put 25 sack plug in and out of where 8 5/8" casing is cut off
- Plan to mud between plugs.
- Plan to set marker at surface in cement.

if 5 1/2" Csg. Comes below top of Queen spot 25 sack Plug @ Queen

SEP 8 1972

C. C. OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harold Kersey TITLE Owner DATE Sept. 6, 1972

APPROVED BY W. A. Gessett TITLE OIL AND GAS INSPECTOR DATE SEP 12 1972

CONDITIONS OF APPROVAL, IF ANY:

as noted

Notify N.M.O.G.C. in sufficient time to witness

Plugging