

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B 9222

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Albritton & Meyer	8. Farm or Lease Name Gilmore State
3. Address of Operator P. O. Box 524, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 17 TOWNSHIP 18-S RANGE 28-E NMPM.	10. Field and Pool, or Wildcat Artesia
15. Elevation (Show whether DF, RT, GR, etc.) 3588 D. F.	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed Work:

1. Load hole with mud.
2. Set 25 sack cement plug at 2235 feet.
3. Set 25 sack cement plug where 5 1/2" casing shot off.
4. Set 25 sack cement plug 1/2 in and 1/2 out of bottom of 8 5/8" casing at 497 feet.
5. Set 10 sack cement plug at top of surface.
6. Set 4" steel marker with following welded on:
Albritton & Meyer, Gilmore St.
1-N-17-18-28.

RECEIVED
AUG 23 1967
O. D. O.
ARTESIA, N.M.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joe Gaurley</u>	TITLE <u>Agent</u>	DATE <u>August 24, 1967</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u></u>	DATE <u>AUG 24 1967</u>
CONDITIONS OF APPROVAL, IF ANY:		