

NEW MEXICO STATE LAND COMMISSION
OFFICE OF THE STATE GEOLOGIST
SANTA FE, NEW MEXICO

MISCELLANEOUS REPORTS ON WELLS

Submit this report in duplicate to the State Geologist or proper Oil and Gas Inspector within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of water shut-off, result of abandonment of well, and other important operations, even though the work was witnessed by the State Geologist or Oil and Gas Inspector. Reports on minor operations need not be signed and sworn to before a notary public, but such operations should be witnessed by an Oil and Gas Inspector if possible.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF SHOOTING WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF WATER SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF ABANDONMENT OF WELL	X		

Artesia, New Mexico, March 24, 1934.

Mr. J. D. Hunter State ~~Geologist~~ Oil and Gas Supervisor,
~~Santa Fe, New Mexico~~ Carlsbad, New Mexico.

Following is a report on the work done and the results obtained under the heading noted above at the
Hurst Well No. 1 in the

SW 1 NE 1 ~~xx~~ COMPANY OR OPERATOR of Sec. 17, T. 18S, R. 28E, N. M. P. M.,
Artesia Oil Field, Eddy County.

The dates of this work were as follows: February 7, 1934, to Feb. 25, 1934.

Notice of intention to do the work was (~~was not~~) submitted on Form SG _____ on
February 6, 19 34 and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Filled hole with mud and surface material from bottom at 2200 feet up to 1700 feet; shot and pulled ~~xxxxxx~~ 1700 feet of 6 & 5/8 casing; finished filling hole with mud and surface material after putting in plug at 1700 feet, same being a wooden plug up to 300 feet; pulled eight inch casing off at 300 feet, filled hole up to 200 feet, shot and pulled out ten inch casing; finished filling hole with surface material to top of ground and placed regulation marker.

Bottom of 6 & 5/8 casing left in hole at 2-40 feet. top at 1700 feet; bottom of eight inch at 565 feet, top at 300 feet; bottom of ten inch at 240 feet and top at 200 feet.

DUPLICATE

Subscribed and sworn to before me this
24th day of March, 19 34

[Signature]
NOTARY PUBLIC.

My commission expires January 22, 1938.

I hereby swear or affirm that the information given above is true and correct.

Name J. D. Hunter
Position Operator
Representing Hurst

Address Artesia, New Mexico.

Remarks:

APR 3 - 1934

APPROVED AS O. K.

BY *[Signature]*

TITLE

