

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>647</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Cine Capitan, Inc. (C. L. F.)</b>	8. Farm or Lease Name <b>Adkins-Williams St.</b>
3. Address of Operator <b>Box 1343, Artesia, New Mexico</b>	9. Well No. <b>5</b>
4. Location of Well UNIT LETTER <b>0</b> , <b>1570</b> FEET FROM THE <b>E</b> LINE AND <b>250</b> FEET FROM THE <b>S</b> LINE, SECTION <b>17</b> TOWNSHIP <b>18S</b> RANGE <b>30E</b> NMPM.	10. Field and Pool, or Wildcat <b>Artesia</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Eddy</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On or about 17 February 1966, plan to plug and abandon this well. The casing is collapsed in this well at 1600'. The tubing is stuck at this point and cannot be pulled. T. D. is 3191'. Tubing is at 2537'. 7" casing is at 1992'. Plan to pump hole full of cement from 2537' to 1910' using 150 sacks. This will completely cover all pay zones and properly isolate each zone. Plan to pull tubing above 1600' and knock off 7" at 1600' and pull same. Plan to spot 25 sack plug at top of salt and cement regulation marker at surface.

RECEIVED

FEB 15 1966

O. C. C.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. C. Parks* TITLE Engineer DATE 14 February 1966

APPROVED BY *M. L. Armstrong* TITLE Oil and Gas Manager DATE FEB 15 1966

CONDITIONS OF APPROVAL, IF ANY: