NEW MEXICO STATE LAN, JFFICE Santa fe, new mexico DEPARTMENT OF THE STATE GEOLOGIST SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

	Artesia,	, N. Mex.,J	an,1, 19.34
Mr. 2. H. Wells,	***		
Santa Fe, New Mexico.			
Dear Sir:			
You are hereby notified that it is our int	tention to abandon	Cummins	
No3 inSE SW of Sec.			
N. M. P. M.,	Oil Field,	Eddy	County.
We plan to commence work onInmedi		-	
The reasons for wishing to abandon the v	vell are as follows:		
This well will only make about or	e-half of a barrel	per day which is	a not

Commercial.

The present condition of the well is as follows:

6-5/8" 2000'. 10-1/4" 400'.

DUPLICATE

The work which we propose to do in abandoning the well is as follows:

Fill hole with mud laden fluid to the bottom of the 6-5/8" pipe then pull the 6-5/8" pipe and fill the hole with mud laden fluid to about 1550'. Then put in about 5' of loose rock and set five sacks of cement with a dump bottom bailer, then fill the hole to 5008 and set three sacks of cement at this point to protect the surface water. Then pull the 10-1/4" pipe and fill the hole to the surface with mud laden fluid and set a piece of pipe and let it extend 4' above the surface as a gegulation marker.

Sincerely yours,

Approved _____ 1-1-____ 19.3 4

Except as follows:

Blanche Beyl by: H. T. Hellman purchaers of: The Sunray 11 Co., Company or Operator. Bve man

Position Supt.

Send communications regarding this well to

State Geologist or Oil and Gas Inspector.

Name T. Hellman, Address Big Spring Pipe and Supply Co., Big Springs, Texas.

TETMORE Dil Co. 1070/5 2390/12