## NEW MEXICO STATE LAND ICL SANTA FE, NEW MEXICO DEPARTMENT OF THE STATE GEOLOGIST SANTA FE

## NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. E. H. Velle		, N. Mex., <b>J</b>	1 9
Santa Fe, New Mexico.  Dear Sir:			
You are hereby notified that it is our intention	on to abandon	Beeson	Well
No			
N. M. P. M.,Artesia	_	_	
We plan to commence work on	August 1,	, 19 <b>32</b>	
The reasons for wishing to abandon the well a			
Well makes about one-half barrel of	oil per day w	hich isn't commer	cial.
-			
The present condition of the well is as follows			
•		h the following e	asing:
10" 500' <del>81</del> " 500'			
The work which we propose to do in aban			
with and laden fluid to about 1550'			t of loose
rock and set five sacks of dement w			fill hole with
and laden fluid to the 500' level a	nd then remove	the 61" casing a	fill hole with nd fill hole
and laden fluid to the 500' level a with mid laden fluid as we pull the of dement at 110' to protect the su	nd then remove pipe. Then pu rface water, to	the 8½" casing a 11 the 10" and se ben fill the hole	fill hole with nd fill hole t three sacks
mud laden fluid to the 500' level a with mud laden fluid as we pull the	nd then remove pipe. Then pu rface water, to	the 8½" casing a 11 the 10" and se ben fill the hole	fill hole with nd fill hole t three sacks
and laden fluid to the 500' level a with mid laden fluid as we pull the of dement at 110' to protect the su	nd then remove pipe. Then pul rface water, the sh pipe for a s	the 82" casing a ll the 10" and se hen fill the hole marker.	fill hole with nd fill hole t three sacks
mud laden fluid to the 500' level a with mud laden fluid as we pull the of cement at 110' to protest the su surface and set a piece of three in	nd then remove pipe. Then pur rface water, the sh pipe for a se Sincerely yours,	the 82" casing a ll the 10" and se hen fill the hole marker.	fill hole with nd fill hole t three sacks to the
and laden fluid to the 500' level a with mid laden fluid as we pull the of coment at 110' to protect the su surface and set a piece of three in	nd then remove pipe. Then pur rface water, the sh pipe for a se Sincerely yours,	the 81" casing a ll the 10" and se hen fill the hole marker.	fill hole with nd fill hole t three sacks to the  SUNHAY OIL CO)
mud laden fluid to the 500' level a with mud laden fluid as we pull the of cement at 110' to protest the su surface and set a piece of three in	nd then remove pipe. Then pur rface water, the sh pipe for a se Sincerely yours,	the 81" casing a ll the 10" and se hen fill the hele marker.	fill hole with nd fill hole t three sacks to the
and laden fluid to the 500' level a with mid laden fluid as we pull the of cement at 110' to protest the su surface and set a piece of three in Except as follows:	mithen remove pipe. Then purface water, the pipe for a second sincerely yours,  H. T. Hellm	the 81" casing as il the 10" and se hen fill the hole marker.  In (Purchaser of Company	fill hole with nd fill hole t three sacks to the  SUNRAY OIL CO) upany or Operator.
and laden fluid to the 500' level a with mid laden fluid as we pull the of cement at 110' to protect the su surface and set a piece of three in	sincerely yours,  H. T. Hellm  Position	the 81" casing as il the 10" and se hen fill the hole marker.  In (Purchaser of Company	fill hole with nd fill hole t three sacks to the  SUNRAY OIL CO) upany or Operator.
and laden fluid to the 500' level a with mid laden fluid as we pull the of cement at 110' to protect the su surface and set a piece of three in Except as follows:	Sincerely yours,  H. T. Hellm  Position  Send communic	the 8½" casing a ll the 10" and se hen fill the hole marker.  In (Purchaser of Com Mellma	fill hole with nd fill hole t three sacks to the  SUNRAY OIL CO) upany or Operator.  well to