

NEW MEXICO STATE LAND FICE
SANTA FE, NEW MEXICO
DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

....., N. Mex., June 9 1932
Artesia

Mr. E. H. Wells
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon Hagsdale Well
No. 1 in NEESE of Sec. 10 Twp. 10 South, Rge. 26 East,
N. M. P. M., Artesia Oil Field, Bddy County.
We plan to commence work on June 10, 1932

The reasons for wishing to abandon the well are as follows:

Will not make 1/3 Bbl oil per day, does not pay to pump.

The present condition of the well is as follows:

Well is in good condition with no water.

Pipe record as follows:

**193' of 10"
580' " 8 1/2"
198 1/2' " 6-5/8"**

The work which we propose to do in abandoning the well is as follows:

Fill hole with mud laden fluid from bottom (2245) to 1939 then set five feet of loose rock and five sacks of cement. Then fill hole with mud laden fluid to 125' and set five feet of loose rock and two sacks of cement, then fill hole with mud laden fluid to the surface and set regulation marker.

DUPLICATE

Sincerely yours,

Approved 6-13 1932

Except as follows:

H. T. Hellman (Formerly Sunray Oil Co)
Company or Operator.

By H. T. Hellman

Position Owner

Send communications regarding this well to

Name H. T. Hellman,

Address Big Springs Pipe and Supply Co.,
Big Springs, Texas

[Signature]
State Geologist or Oil and Gas Inspector.