NO. OF COPIES RECEIVED	**			
				Form C-193
DISTRIBUTION SANTA FE		FFFTV	TON COMMISSION	Supersedes Old C-102 and C-103
FILE	NEW MEXIC	OIL CONSERVAT	TON COMMISSION	Effective 1-1-65
			. Name and	
U.S.G.S.		APR 3 0 19	975	5a. Indicate Type of Lease
LAND OFFICE		• • • • • • • • • • • • • • • • • • • •		State X Fee.
OPERATOR /	1	o. c. c		5. State Oil & Gas Lease No.
		APPERIA OF	·	E-1313
SUNDR (DO NOT USE THIS FORM FOR PRO USE "APPLICATION"	Y NOTICES AND REPOSALS TO DELECTION FOR PERMIT -" (FORM C-1	ORTS ON WELL	S DIFFERENT RESERVOIR.	
1.		,		7. Unit Agreement Name
OIL X GAS WELL	OTHER.			
2. Name of Operator				8. Farm or Lease Name
ARWOOD, LTD.				Amerada State
3. Address of Operator Petroleum Building-	Tower Suite, R	oswell, Ne	ew Mexico	9. Well No.
4. Location of Well				1-9
	660 FEET FROM THE	North	2310	10. Field and Pool, or Wildcat Artesia
West	20 TOWNSHIP	18S	28E	NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)				
		D.F.	GR, etc.)	12. County Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN	TENTION TO:		SUBSEQ	JENT REPORT OF:
		_ 	<u> </u>	
PERFORM REMEDIAL WORK	PLUG AND ABA	NDON REMED	IAL WORK	ALTERING CASING
TEMPORARILY ABANDON		<u></u>	NCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING	TEST AND CEMENT JOB	
		[] OTH	ER	
OTHER	· · · · · · · · · · · · · · · · · · ·			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE PHI 5 103				
worky SEE NOTE 1103.				
315', 10 3/4" csg Pulled				
515.9' 8 5/8" csg. with 50 sx.				
2325' 5 1/2" csg. with 100 sx. TD 2441 PBTD 2288 Perforations 2098-2116, 2262-2280				
Periorations 2096-	2110, 2202-220	U		
#1) Spot 100' cement plug across perforations.				
2) Shoot off 5 1/2"casing.				
3) Spot 100' cement plug across stub of 5 1/2" and mud between plugs.				
4) Spot 100' cement plug across shoe of surface and mud between plugs.				
5) Set 25' surface plug and marker with mud between plugs.				
6) Clean up location.				
o, crean ap rocat	,1011•			
Work to commence May 8 to 9th.				
* minimum of 20 5x or if flowing water a BP w/30 of Coment will be required shot and pulled 51 sto or 1600 53 ye. Ran taking back & 1650 at 35/54				
* minimum 1 20 5x or of flewing water at By				
Shot and pulled 51 sto or 1600 53 ye, Ran Thing back & 1650 but 35/54 550 /50/5x, 25:30 at surface. Ga had to a hote in it app. 1550 and two				
550 /50/rv 38: 30	at surbone (es had	a hope in it	Asp. 1550 alt
hele to see a	1. 1 = 14	· · · · · · · · · · · · · · · · · · ·		So'. Al I -
holes at 1590-95 about 5 hot, Were line plus at 1967 3006 Next on Top 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
	. 0			
SIGNED . M. S		Agen	_	4/29/75
SIGNED C , ,	7 ′ r	ITLE		4/29/75
1107	4			•••

CONDITIONS OF APPROVAL, IF ANY:

SUPERVISOR, DISTRICT. II

MAY 1 1975

Notify 11.M.O.C.C. in sufficient time to witness