

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

JAN 6 1971

O. G. O.
ARTESIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. 647	
7. Unit Agreement Name -	
8. Farm or Lease Name Resler Yates State	
9. Well No. 30	
10. Field and Pool, or Wildcat Artesia	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water injection
2. Name of Operator AMERICAN PETROFINA COMPANY OF TEXAS ✓
3. Address of Operator Box 1311, Big Spring, Texas 79720
4. Location of Well UNIT LETTER TI , 1070 FEET FROM THE East LINE AND 2390 FEET FROM THE South LINE, SECTION 21 TOWNSHIP 18S RANGE 28E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3587 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Start work approx. 2-1-71

Spot 50 sk cement plug on bottom (TD 2189) through 2" EUE tubing using mud laden fluid as displacing medium.

Cut off 4-1/2" OD casing @ 680' - Spot 25 sk cement plug @ 680' (csg. stub)

Pull 4-1/2" casing

*** Spot 25 sk. cement plug @ 121' (bottom of 7")**

Place 10 sk cement plug in top of 7" casing @ set 4-1/2" pipe marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cliff Chapman **Cliff Chapman** TITLE Petroleum Engineer DATE 1/5/71

APPROVED BY W. A. Gressett TITLE Oil and Gas Supervisor DATE JAN 7 1971

CONDITIONS OF APPROVAL, IF ANY: * is noted above