

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/-
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
647

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
American Petrofina Company of Texas	Resler Yates State
3. Address of Operator	9. Well No.
Box 1311, Big Spring, Texas 79720	23
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER 0, 1070 FEET FROM THE South LINE AND 1570 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 18S RANGE 28E NMPM.	Artesia
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 4½" cast iron bridge plug in 4½" casing at 2103'. Dumped 2 sx. cement on top of bridge plug. Ran 2" NUE tubing to 2085' and loaded hole with 10# mud. Left 4½" casing (cemented from TD to surface) in hole. Put 5 sx. cement plug in top of 4½" casing and set 4" pipe marker.

RECEIVED

JCC/ga

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cliff Chapman **Cliff Chapman** TITLE Petroleum Engineer DATE July 26, 1967

APPROVED BY R. F. Stamm TITLE Secretary DATE July 26, 1967

CONDITIONS OF APPROVAL, IF ANY: