NO. OF COPIES RECEIVED			<u>د.</u>	Form C-103
DISTRIBUTION				Supersedes Old C-102 and C-103
SANTA FE	17		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	1			
U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE				State 🗙 Fee
OPERATOR	1			5. State Oil & Gas Lease No.
	- L_ <i>L</i>	 i		
(DO NOT USE THIS FO	SU APP		Y NOTICES AND REPORTS ON WELLS posals to drill or to deepen or plug back to a different reservoir. ion for permit	
1.				7. Unit Agreement Name
OIL GAS WELL WEL			OTHER-	
2. Name of Operator			i internet in the second se	8. Farm or Lease Name
AMERICAN PETROFI	NA	сом	PANY OF TEXAS	McNutt State
3. Address of Operator				9. Well No.
Box 1311 Big S	bri	ng.	Texas 79720	-
4. Location of Well	<u> </u>	-01		10. Field and Pool, or Wildcat
UNIT LETTER K			2315 FEET FROM THE WEST LINE AND 2434 FEET FROM	Artosia
THE SOUTH		FCTIC	N TOWNSHIP RANGE RANGE NMPM.	
			RANGE NMPM.	
	Π	\overline{U}	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	////	///	3568 Gr	Eddy Allilli
16.	Che	<u>مد د</u>		
NOTI			Appropriate Box To Indicate Nature of Notice, Report or Ot	
NOTIO	UE U		SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	ך		PLUG AND ABANDON	ALTERING CASING
TEMPORARILY ABANDON	Ĩ		COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	ī		CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
	_		OTHER	۲ -٦
OTHER			UIHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-11-69 kan 2ⁿ EUE tubing to TD 2079' and picked up to 1980'. Mixed mud and spotted 50 mx cement plug on bottom. Pulled tubing up to 1540 and spotted 25 sx cement. Pulled tubing up to 1100 and spotted 50 sx cement.

6-2-69 Checked cement fillup and found at 600[°].
Shot off 7" casing at 558[°] but could not pull. Mixed 50 ax cement and spotted at 558[°].
Put 10 ax cement plug in top of 7" casing and set 4-1/2" pipe marker.

RECEIVED

AUG 1 9 1969

C. C. C.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY APPROV

CONDITIONS OF APPROVAL, IF ANY: