

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

**RECEIVED**  
 NEW MEXICO OIL CONSERVATION COMMISSION  
 JUL 16 1968  
 O. C. C.  
 ARTESIA OFFICE

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 647

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator AMERICAN PETROFIDIA COMPANY OF TEXAS	8. Farm or Lease Name Lackawanna State
3. Address of Operator Box 1311, Big Spring, Texas 79720	9. Well No. 6
4. Location of Well UNIT LETTER <b>H</b> , <b>2390</b> FEET FROM THE <b>North</b> LINE AND <b>242</b> FEET FROM THE <b>East</b> LINE, SECTION <b>21</b> TOWNSHIP <b>18S</b> RANGE <b>28E</b> NMPM.	10. Field and Pool, or Wildcat Artesia
15. Elevation (Show whether DF, RT, GR, etc.) 3395 Gr.	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 50 sk cement plug on bottom through 2" tubing using 10# mud as displacement fluid.
2. Place 5 sk cement plug at surface and set 4-1/2" pipe marker in top of 7" casing.

\* 7" casing 10' from bottom 300' at 200' depth  
 10' to 15' at 200' depth

JCC:ft

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <i>J. M. Denson</i>	J. M. Denson	Asst. District Mgr. of Prod.
DATE	7-15-68	
APPROVED BY <i>W. A. Gressett</i>	W. A. Gressett	OIL CONSERVATION INSPECTOR
DATE	JUL 20 1968	
CONDITIONS OF APPROVAL, IF ANY: <i>+</i>		