

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
--

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator American Petrofina Company of Texas ✓ 3. Address of Operator Box 1311, Big Spring, Texas 79720 4. Location of Well UNIT LETTER H 2390 FEET FROM THE North LINE AND 242 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 18S RANGE 28E NMPM.	7. Unit Agreement Name -- 8. Farm or Lease Name Lackawanna State 9. Well No. 6 10. Field and Pool, or Wildcat Artesia 15. Elevation (Show whether DF, RT, GR, etc.) 3595 Gr. 12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-30-68 Ran 2" EUE tubing to 2232' and circulated hole with 10# mud. Pulled tubing up to 2170' and spotted 50 sack cement plug.

8-17-68 Shot off 7" OD casing at 1022' and pulled one joint. Spotted 25 sack cement plug over casing stub at 1000'. Pulled 7" casing up to 275' and spotted 25 sack cement plug (base of 10"). Placed 5 sack cement plug in top of 10" casing and set pipe marker.

JCC/jls

RECEIVED
OCT 11 1968
O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED	<u>J. M. Denson</u>	TITLE	<u>Asst. Dist. Mgr. of Production</u> DATE <u>October 10, 1968</u>
APPROVED BY	<u>D. L. Stunt</u>	TITLE	<u>OIL AND GAS INSPECTOR</u> DATE <u>10-10-68</u>
CONDITIONS OF APPROVAL, IF ANY:			