Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICTI

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

WELL API NO. P.O. Box 2088 CFIVED Santa Fe, New Mexico 87504-2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE JUN 1 1 1992 FEE L DISTRIC: III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. O. C. D. 647 SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) McNutt 10 1. Type of Well: WELL X WELL 2. Name of Operator 8. Well No. Plains Petroleum Operating Company 3. Address of Operator 9. Pool name or Wildcat 415 West Wall, Suite 1000 Midland, Texas 79701 Artesia Queen GSA 4. Well Location K : 1650 Feet From The South Line and 1750 \_\_ Feet From The <u>West</u> Line 21 Range 28E Eddy Township **NMPM** Section County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Gr 3572 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING REMEDIAL WORK **CHANGE PLANS** TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. RIH w/2 3/8" 4.7# tbg, 2 3/8" X 5 1/2" R pkr, (2083) land btm tbg @ 2786. 5-2-92 Close BOP. Acidize SA & Premier w/1000 gal 15% NEFE HCL. 5-7-92 RIH w/inflatable pkr & tbg. Acidize Up SA w/1500 gal 15%- NEFE HCL followed by 16 bbl 2% KCL flush. RIH w/2 7/8" inflatable pkr, 2 7/8" tbg. Acidize Premier w/1000 gal 7 1/2%5-8-92 NEFE HCL. Frac w/6000 gal X-link gel pad followed by 2000 gal X-link gel w/24000# 12/20 Brady Propant. Flush w/576 gal gel. 5-9-92 Release pkr, POOH w/tbg & pkr. RIH w/2 7/8" tbg w/notched shoe, tag sd @ 2388'. Clean debris from shoe. Continue to clean out (tbg plugged) I hereby certify that the information above is true and complete to the best, of my knowledge and belief. DATE 06-08-92

Office Manager/Tech SIGNATURE

**ТЕГЕЗТЮНЕ НО.** (915)683-4434

(This space for State Use)

TYPE OR PRINT NAME

ORIGINAL SIGNED BY

MIKE WILLIAMS

JUN 1 6 1992

- DATE

AITROVED BY-SUPERVISOR, DISTRICT IS

Bonnie Husband

CONDITIONS OF AFFROVAL IF ANY:

. 15 · \$ · • \$

and the second of the second o

JUN 0 9 1992

Release RBP, ND BOP. RIH w/2 3/8" 4.7# tbg w/BPMA, perf sub, SN, land @ 2675'. Btm tbg @ 2710'. RIH w/2" X 1 1/2" X 10' pump, rods. Space pump & hung on.

5-11-92 Repair electrical problem. Begin testing well.

JUN 0 9 1998 JUN 0 9 1998