NO. OF COPIES RECEIVED		Form C-103	
DISTRIBUTION		Supersedes Old C-102 and C-103	
SANTA FE '	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65	
FILE			
U.S.G.S.	4. 1976	5a. Indicate Type of L	
LAND OFFICE	1417	State 🕱	Fee
OPERATOR .		5. State Oil & Gas Lea	
		• 64	47
SUNDS (DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS		
1.	TOW TORY ERMIT = TOWN OF TORY SOUNT THOSE	7. Unit Agreement Nar	me
OIL GAS WELL WELL	OTHER. Water Injection Well	•	
2. Name of Operator	8. Farm or Lease Nam	8. Farm or Lease Name	
AMERICAN PI	Welch Duke State		
3. Address of Operator	9. Well No.		
Box 1311, H	sig Spring, Texas 79720	15	
4. Location of Well	03.5	10. Field and Pool, or	r Wildcat
D	228 FEET FROM THE North LINE AND 272 FEET FRO	Artesia	
UNIT LETTER,	FEET FROM THE STATE CINE AND		
West	ION 28 TOWNSHIP 188 RANGE 288 NMPN		
THE WEST LINE, SECTI	ION TOWNSHIP RANGE AOB NMPN	" <i>((((((((((((((((((((((((((((((((((((</i>	(((((((
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
	•	Eddy	
16. Check	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data	
		IT REPORT OF:	
NOTICE OF I	ATEM TON TO.		
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING C	ASING

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CHANGE PLANS

## Start work approx. 9/7/70

- 1. Spot 50 sk cement plug on bottom (TD 2030) through 2" MUE tubing using mud laden fluid as displacing fluid.
- 2. Cut off 4-1/2" casing at 1560' and spot 25 sk cement plug at that point.
- 3. Pull 4-1/2" casing.
- 4. Pull 8-5/8" casing (670')
- 5. Spot 25 sk cement plug at 6701

	٦.	Spot 23 by centure pade at 0,0
	6.	Spot 25 sk cement plug at 273' (bottom of 10-3/4" casing)
	7.	Place 10 sk cemant plug in top of 10-3/4" casing & set 4-1/2" OD marker.
18. I hereby certif	y that i	the information above is true and complete to the best of my knowledge and belief.
APPROVED BY		OVAL, IF ANY: