

March 7, 1969

E. P. Campbell
P. O. Box 763
Hobbs, New Mexico

Re: Cockerham Well No.1-A,
34-18-26, Dayton-Abo Pool
Eddy County, New Mexico

Gentlemen:

On March 6, 1969, an inspection was made of the subject well. Said inspection revealed a gas leak in the 4½ inch casing below the well head. Further, the inspection showed that the tanks have been drained onto the surface of the ground rather than to a pit as required. The fluid drained has run up to 200 feet from the tanks.

Please have the casing leak repaired immediately and install the necessary equipment to insure that the tanks will be drained to the pit in the future.

If there are any questions on this matter, please do not hesitate to call upon me.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets
Geologist

RLS:jw

March 7, 1969

El H. Campbell
Box 703
New Mexico

Mr. Campbell
34-13-16, Dayton-Abso 1001
El H. Campbell, New Mexico

Dear Mr. Campbell:

On March 6, 1969, an inspection was made of the subject well. Said inspection revealed a gas leak in the 4 inch casing below the well head. Further, the inspector showed that the casing have been drilled into the surface of the ground rather than as a pit as reported. The fluid drained has run up to 200 feet from the casing.

Please have the casing leak repaired immediately and inspect the necessary equipment to insure that the tank will be drained to the pit in the future.

If there are any questions on this matter, please do not hesitate to call upon me.

Very truly yours,

THE CONSERVATION COMMISSION

R. D. Stewart
Geologist

Enc. 1