

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
--

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> WELL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER- Injection Well	7. Unit Agreement Name --
2. Name of Operator AMERICAN PETROFINA COMPANY OF TEXAS	8. Farm or Lease Name Levers State
3. Address of Operator Box 1311, Big Spring, Texas 79720	9. Well No. 10
4. Location of Well UNIT LETTER A , 1061 FEET FROM THE South LINE AND 2271 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 18S RANGE 28E NMPM.	10. Field and Pool, or Wildcat Artesia
15. Elevation (Show whether DF, RT, GR, etc.) 3660 Gr.	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-23-69 Ran 2-3/8" tubing to 2265'.
Mixed mud and spotted 25 sx cement @ 2265'.
6-24-69 Tagged top of cement at 1970'.
7-3-69 Shot off 4-1/2" casing at 1802'.
7-5-69 Spotted 25 sx cement plug at 1800'. Pulled 4-1/2" casing up to 750'
and spotted 25 sx plug.
Finished pulling 4-1/2" casing.
7-7-69 Shot off 8-5/8" casing at 398' and pulled up to 250'.
Spotted 25 sx cement plug at 250'.
Finished pulling 8-5/8" casing.
Put 10 sx cement plug at surface and placed 4-1/2" pipe marker.

RECEIVED

AUG 19 1969

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. M. Denson TITLE Asst. Dist. Mgr. of Production DATE August 18, 1969

APPROVED BY [Signature] TITLE [Signature] DATE AUG 27 1969

CONDITIONS OF APPROVAL, IF ANY: