

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO
DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

.....**Artesia**....., N. Mex., **Feb. 20,** 19**34**

Mr. **E.H. Wells**
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon **Kaseman** Well
No. **3** in **NW. SW.** of Sec. **4** Twp. **18 S**, Rge. **28e**,
N. M. P. M., **Artesia** Oil Field, **Bddy** County.
We plan to commence work on **Immediately**, 19.....

The reasons for wishing to abandon the well are as follows:

"oil making 1/8 barrel and is not a commercial producer"

The present condition of the well is as follows:

10 1/4" casing 297' 35Lb 8 thd

6-5/8 casing has been pulled and tubing run back tried to pump without casing to increase production but have been unable to do so.

The work which we propose to do in abandoning the well is as follows:

Fill the hole to 1500'
Fill the hole to 1500' with mud laden fluid put in 5 feet of rock
set 5 sacks of cement with dump bottom bailer. Fill hole to 500'
with mud laden fluid put in 5' of rock and set 3 sacks of cement
with dump bottom bailer and fill hole to top with mud laden fluid
set a piece of pipe extending 4' above ground as a permanent marker

DUPLICATE

Sincerely yours,

Approved **MAR 2 - 1934** 19.....

Except as follows:

Blanche Beyl
Company or Operator.

By **A.T. Hellman**

Position **plugging Contractor**

Send communications regarding this well to

Name **A.T. Hellman**

Address **Box 223 Big Spring Tx**

[Signature]
State Geologist or Oil and Gas Inspector.