

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

DEC 29 1970

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-3823</b>	
7. Unit Agreement Name <b>--</b>	
8. Farm or Lease Name <b>Solt State</b>	
9. Well No. <b>3</b>	
10. Field and Pool, or Wildcat <b>Artesia</b>	
12. County <b>Eddy</b>	

## SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>AMERICAN PETROLEUM COMPANY OF TEXAS</b>
3. Address of Operator <b>Box 1311, Big Spring, Texas 79720</b>
4. Location of Well UNIT LETTER <b>F</b> , <b>1506</b> FEET FROM THE <b>North</b> LINE AND <b>1696</b> FEET FROM THE <b>West</b> LINE, SECTION <b>4</b> TOWNSHIP <b>18S</b> RANGE <b>23E</b> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <b>3653 GL</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Start work approximately 1-11-71

Spot 50 sx cement plug on bottom (TD 2260) through 2" EUE tubing using mud laden fluid as displacing medium.

Spot 25 sx cement plug at 883' (Bottom of 8-5/8" casing).

Cut off 8-5/8" casing at 525' and pull.

Spot 25 sx cement plug at 525 (8-5/8" casing stub)

Place 10 sx cement plug at surface and set 4-1/2" pipe marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. M. Denson TITLE Asst. Dist. Mgr. of Production DATE December 29, 1970

APPROVED BY W. A. Givens TITLE OIL AND GAS INSPECTOR DATE DEC 31 1970

CONDITIONS OF APPROVAL, IF ANY: spot a 25 sack plug 1350-1450 799 Green