

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-02608

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E-7179

7. Lease Name or Unit Agreement Name
STATE E-AI

8. Well No.
1

9. Pool name or Wildcat
EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator <u>Phillips Petroleum Company</u>
3. Address of Operator <u>4001 Penbrook Street Odessa, TX 79762</u>	4. Well Location Unit Letter <u>E</u> : <u>1659.9</u> Feet From The <u>NORTH</u> Line and <u>330</u> Feet From The <u>WEST</u> Line Section <u>5</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>EDDY</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3660.7' GL</u>	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ACIDIZE ABO, ADD PERFS. & ACIDIZE PERFS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07/05/99 MIRU DDU
07/06/99 COOH W/RODS, START UNFLNGNG WH, REFLNG WH, GIH W/RODS, HO, RD, MOVE TO GRAYBURG #10
07/08/99 MIRU DDU, COOH W/RODS, UNFLNG WH, NU BOP, COOH W/TBG.
07/09/99 FIN COOH W/TBG, PU GIH W/BIT & SCRPR TAG @ 6212', COOH, GIH W/BIT & TBG, MIRU DAVIS REV UNT, PMP 52 BBL TRY T/BRK CIRC, GOING REV, SWITCH T/CONVENTIONAL & CO T/PBTD 6228', RD REV UNT, SOOH W/TBG.
07/10/99 FIN COOH W/SCRPR, MIRU TBG TSTRS, TST W/PKR & TBG, FOUND TBG LK 3 JTS F/BTM, RDMO TBG TSTRS, SET PK 6095', LD & TST BKSIDE T/500# OK, RU SWAB, MK 6 SWAB RUNS, FL @ 5800'.
07/11/99 MIRU HES ACID EQMT, TST LNS, PMP 1000 GAL 15% CCA ACID, 500# RK SLT IN 12 BBL GEL BRINE, 1000 GAL A 500# SALT 12 BBL GEL BRINE, 1000 GAL ACID, FLUSH W/26 BBL FW, ISIP VAC MAS PRESS 3500# AVG 2500# A RATE 5 BPM, RDMO HES, RU SWAB, GIH W/FL @ 4800', REC 13.5 BBL W/FL @ 5900', RD SWAB.
07/12/99 CREW OFF 24 HRS.

(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature]
TYPE OR PRINT NAME Larry M. Sanders

TITLE Senior Regulation Analyst DATE 7/27/99
TELEPHONE NO. (915) 368-1488

(This space for State Use)

APPROVED BY [Signature] TITLE District Supervisor DATE 8-11-99
CONDITIONS OF APPROVAL, IF ANY:

STATE E -AI #1 CONTINUED

07/13/99 REL PKR, TAG SALT FILL PMP FW, RE TAG @ 6228', COOH W/PKR, MIRU HES PERF EQMT, GIH PERF: 6101-6112', 11' 48 SHOTS, 6086-6072', 4' 20 SHOTS, 6030-6038', 8' 36 SHOTS W/PREM CHRGs ON 90 DEG PHASNG & 4 SPF, RDMO HES, GIH W/RBP & PKR, PROBLEMS GETTING RBP DWN, COOH, CHG DRAG BLKS ON RBP, GIH FIND PLACE WHERE RBP & PKR WOULD SET, SET RBP @ 6149' PKR @ 6137', TST PKR T/1000# OK, MOVE PKR T/5957', LD & TST BKSIDE T/500# OK.

07/14/99 MIRU HEA ACID EQMT, TST LINES, PMP 2500 GAL 15% CCA ACID DROPPING 150 1.3 SPG BALLS @ 5/BBL, FLUSH W/29 BBL FW, MAX PRESS 1128# AVG PRESS 405# MAX RATE 6.9 BPM AVG RATE 4.5 BPM, ISIP VAC, RDMO HES, RU SWAB, W/FL @ 4700' SWAB DRY, WAIT 1 HR, FL ENTRY + 1300', SWAB DRY, WAIT 1 HR W/FL ENTRY 450', SWAB DRY, WAIT 1 HR W/FL ENTRY 250', RD SWAB, REL PKR, RETRIEVE RBP, COOH, GIH W/PROD TBG, ND BOP, FLNG UP WH.

07/15/99 GIH W/PMP & RODS, SPACE OUT, HANG ON, LD & TST, RDMO DDU, LEAVE PMPG NO TST.

07/16/99 PMP 20 HRS NO TST TEMP DROP F/REPORT

07/27/99 07/24/99 PMP 24 HRS, TST 51 BOPD 30 BWPD 274 MCF
07/25/99 PMP 24 HRS, TST 52 BOPD 30 BWPD 293 MCF
07/26/99 PMP 24 HRS, TST 42 BOPD 30 BWPD 307 MCF
COMPLETE DROP F/REPORT