Submit 3 Copies to Appropriate District Office Submit 3 Copies to Appropriate District Office State of New Mexico Energy Minerals and Natural Resources Department of the Control of the	rtment Form C-103 Revised 1-1-89
District Office OH CONTROL DIVISION	,
DISTRICTI OF AND SERVATION DIVISION	WELL API NO. 30-015-02619
DISTRICT II THE RECEIVED P.O. Drawer DD, Artesia NM 88218 - ARTESIA	5. Indicate Type of Lease STATE X FEE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, MM 87410	6. State Oil & Gas Lease No.
SUNDRY NO HOLES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Empire Abo Unit "J"
1. Type of Well: OIL GAS WELL OTHER	Empire Abo onit 3
2. Name of Operator /	8. Well No.
BP America Production Company /	21
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	9. Pool name or Wildcat Empire Abo
4. Well Location Unit Letter E: 1990.48 Feet From The N Line and 660 Feet From The W Line	
Section 6 Township 18S Range 28E 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Eddy County
3640.72' GR	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND CE	MENT JOB
OTHER: OTHER: Workover	
12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propos work) SEE RULE 1103.	
TD: 6202' PBD: 6180' CIBP: 6075' PERFS: 5646-5770' (OLD) 5797'-6025' (NEW)	
9/9/02 MIRUPU. Drop standing valve.	
9/10/02 Perforate tubing. Swab well.	
9/11/02 NDWH. NUBOP. TOH w/tbg. 9/12/02 TIH w/ bit & scraper. Test tbg. in hole. Tag @ 6036'.	
9/13/02 RU & perf. w/ 2 JSPF from 5797'-6025'.	
9/16/02 Pump 6000 gals. w/ 400 BS 5 bbls/min.	
9/17/02 Clean out FRAC balls to 6036'.	
9/18/02 NUWH. RIH w/ swab. Swab well dry. 9/19/02 Set tbg. @ 5968'. SN @ 5973'. RTP. In 24 hrs. pmp 0 BO, .1 BW, 190 mcf.	
9/19/02 Set tog. @ 5908 . SN @ 59/3 . KIP. In 24 nrs. piiip 0 bo, .	1 BW, 190 MCI.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Vichi Owers TITLE Administrative A	10/17/00
TYPE OR PRINT NAME Vicki Owens for Kellie D. Murrish	ssistant DATE 10/17/02
	TELEPHONE NO. 505-394-1650
ORIGINAL SIGNED BY TIM W. GUM	
ORIGINAL SIGNED BY TIM W. GUM APPROVED BY TITLE	OCT 2 5 2002