

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Geology, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

CLSF
OP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

OCT 29 '90

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-7179
7. Lease Name or Unit Agreement Name West Artesia Grayburg Unit Tr. 5
8. Well No. 10
9. Pool name or Wildcat Artesia Queen Grbg SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Marbob Energy Corporation
3. Address of Operator P. O. Drawer 217, Artesia, NM 82810
4. Well Location Unit Letter <u>K</u> : <u>2200</u> Feet From The <u>South</u> Line and <u>2200</u> Feet From The <u>West</u> Line Section <u>8</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>Eddy</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/5/90 Plug and abandon as follows:

Set 25 sack plug at 2100'. Tagged plug at 1716'. Circ hole w/mud. Perfed csg at 1442'. Squeezed perf w/280sx cmt. Perfed cst at 400' and squeezed w/120sx cmt. Circ cmt.

Will notify when location is ready for inspection.

Post IO-2
11-9-90
PvA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rhonda Nelson TITLE Production Clerk DATE 10/19/90
TYPE OR PRINT NAME Rhonda Nelson TELEPHONE NO. 748-3303

(This space for State Use)

APPROVED BY Johnny Robinson TITLE OIL AND GAS INSPECTOR DATE 3-4-92
CONDITIONS OF APPROVAL, IF ANY: OKGW