(N	orm 3160-5 ovember 1983) ormerly 9-331)	DEPART	MEI OF THE			2 200	Budget Bureau Expires August	31, 1985	
-			AU OF LAND MAN	all and the second seco	r mg		NM 23413	AND BURIAL NO.	
	(Do not use	INDRY NO	TICES AND RE	PORTS (N WELLS	8	. IF INDIAN, ALLOTTES	OR TRIBE NAME	
1.	(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) RECEIVED						7. UNIT AGREEMENT NAME		
2.	WELL X WELL OTHER						8. FARM OR LEASE NAME		
	DEKALB Energy Company JAN 20'89						Dunn "A"		
3.	800 Contra	O. C. D.				9	9. WELL NO.		
4.	800 Central, Odessa, Texas 79761 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface					1	10. FIELD AND POOL, OR WILDCAT		
	1980' FNL & 660' FEL, Sec. 12, T-18s, R-28e					1	1. SEC., T., E., M., OR B SURVEY OR AREA	LE. AND	
14.	PERMIT NO. 15. ELEVATIONS (Show			w whether DF, RT, GR, etc.)			Sec 12, T-18 2. COUNTY OR PARISH	S. R-28e 13. state	
			3636 GR				Eddy	New Mexico	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data								
	NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:				
	FRACTURE TREAT	T-OFF .	PULL OR ALTER CASING MULTIPLE COMPLETE		WATER SHUT-OFF		REPAIRING W		
	SHOOT OR ACIDIZ	Е	ABANDON*		FRACTURE TREATMENT SHOOTING OR ACIDIZING	;	ALTERING CA ABANDONMEN		
	REPAIR WELL CHANGE PLANS (Other)				(Other) (Note: Report results of multiple completion on Well				
17.	Completion or Recompletion Report and Log form.) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)								
	11-28-88: Perf @ 2178, 80, 86, 92, 96, 98, & 2202'. Set RTTS pkr @ 2132' & RBP @ 2300' & acidized perfs w/1000 gals 20% NE-FE acid.								
	11-29-88: Swab to test new perfs. Swabbed 80 bbls wtr w/no oil show.								
	11-30-88:	1-30-88: Pulled tbg & RTTS pkr. Ran tbg & spotted 25' sand on top of RBP. Set retainer @ 2096' & pumped sx Hal-lite cmt thru retainer & perfs followed w/150 sx "C"							
	12-1-88:	2-1-88: Ran temp. log. TOC 485'.							
	12-2-88: Drld retainer & cmt in 4 1/2". Press up to 450#. Held OK. Wash sand off RBP, pull RBP.								
	12-3-88:	Returned we	11 to product	ion.					
~	I haraba aartien f	hat the foregoing is							
. (7.	STONDER &	1		umre Ch	ief Production Cle	ar le	1 0 0		
	This area and			TILE <u>UN</u>	TEL LINGUELION CLE	= FK	DATE 1-9-8		
		ederal or State offi			A	CCEPT	TED FOR RECO	PD.	
	APPROVED BY _ CONDITIONS OF	APPROVAL, IF A		ITLE	, ,		DATE	-	
						į.	AN 1 7 1989		
			**		D C: L				

*See Instructions on Reverse Side

\$J\$ CARISBAD, NEW MEXICO