(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

SHOOTING OR ACIDIZING

(Other)

Perf w/2 SPF @ 2387'-92', 2610'-17', 2622-28', 2664'-70'. Set packer @ 7-21-77 2341', and fractured well with 40,000 gal. gelled wtr. & 80,000# SN. in 7 stages. Cleaned well out and returned to production.

8-6-77 Tested 8 BO and 84 BW.

ABANDON*

CHANGE PLANS

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

RECEIVED
AUG 1 6 1977

ABANDONMENT*

U.S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

| 18. I hereby certify that the foregoing is true and correct | TITLE Engineer Assistant | DATE 8-15-77 |
|---|--------------------------------|-------------------|
| (This space for Federal op State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: | TITLE ACTING DISTRICT ENGINEER | DATE AUG 1 8 1977 |