

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Reswell, N.M.Lease No. 045428Unit 2

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 17, 1958

**Donohue-Fed.** is located 1610 ft. from N line and 330 ft. from E line of sec. 21

SW, NW, 21 168 29E NMPN  
(Sec. and Sec. No.) (Twp.) (Range) (Meridian)

High Lonesome Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The following work conforms to our conversation to plug and abandon this well.

- (1) Shot and pulled 5 1/2" casing at 1790'
- (2) Ran tubing to 1830' on outside of casing. Cemented with 75 sx reg cement with Halliburton.
- (3) Set 5 sx plug @ base of salt (900')
- (4) Set 5 sx plug @ 400' - Surface casing shoe
- (5) Set 5 sx plug and dry hole marker in top surface.

RECEIVED

DEC 13 1968

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Utex Exploration Co.Address Box 1268Artesia, New MexicoBy Archie M. SpeerTitle Prod. Supt.

