J. O. COPIES RECEIVED	7	and the second second	Form C-103
DITRIBUTION	1	RECEIVED BY	Supersedes Old C-102 and C-103
, FE V	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65
, E IV	7	OCT 111983	
U.S.G.S.	7	001 11 1000	Sa. Indicate Type of Lease
LAND OFFICE	1	O. C. D.	State VV Fee
OPERATOR 1	┪	1	5. State Oil & Gas Lease No.
OPERATOR		ARTESIA, OFFICE	B-5524-13
CHANDRY MOTICES AND DEPORTS ON WELLS			
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR DEACH PROPOSALS.)			
			7. Unit Agreement Name
OIL GAS WIW - PA			WEST LOCO HILLS GRB #4
2. ame of Operator			8. Form or Lease Name SD UT
			Tract 27
NEWMONT OIL COMPANY  3. Address of Operator			9. Well No.
			1
P. O. BOX 1305 ARTESIA, NEW MEXICO 88210			10. Field and Pool, or Wildcat
			Loco Hills (O.G.SA)
UNIT LETTER ,			11111111111111111111111111111111111111
THE FWL LINE, SECTION 1 TOWNSHIP 18 RANGE 29 NMPM.			
	15. Elevation (Show whether	DE RT CR etc.)	12. County
	15. Elevation (5.000 whether 3524'	Dr, Rr, OR, elecy	Eddy
			, , , , , , , , , , , , , , , , , , , ,
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
	INTENTION TO:		IT REPORT OF:
			_
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
PULL OR ALVEN CASING	<del></del>	OTHER P&A	
OTHER			
<del></del>			
17. Describe Proposed or Completed	Operations (Clearly state all pertinent det	ails, and give pertinent dates, includir	ag estimated date of starting any proposed
work) SEE RULE 1703.			
7/18/83Tagged bottom. Spotted 100 sks cement w/2% Calcium. WOC. Tagged plug at 2392'.			
Spotted 50 sks cmt w/2% Calcium. WOC.			
10% C. I. CT FOO not MOC Progues			
7/19/83Tagged plug at 1857'. Squeezed 35 sks cmt w/2% Calcium. SI 500 psi. WOC. Pressure			
tested plug - no plug. Squeezed 50 sks cmt w/2% Calcium. SI 400 psi. WOC.			
$\sim$ 5 / 1 $\sim$ 0.10751 Gaussian FO also out $\sim$ 1/2			
7/20/83Pressured up to 500 psi. Plug okay. Perf. 4 shots @ 1075'. Squeezed 50 sks cmt w/25			
at 724'. SI 400 psi. WOC. Pressure to 500 psi. Plug held. Perf 4 shots at 475'. Tagged plug at 875'. Bullhead squeezed 50 sks cmt w/2% Calcium. SI - no pressure.			
Tagged plug a	at 875'. Bullhead squeez	ed 50 sks cmt w/2% Calc	ium. SI - no pressure.
7/21/83Pressure to 5	500 psi. Tagged plug at	345'. Mixed 15 sks cmt	for a top hole plug.
Installed P&A			
		and the second s	· * *
Location cleaned, seeded and ready for inspection.			First His 3
			7.5 1.8
			reconstruction of
			18 424
			1
18. I hereby certify that the informati	on above is true and complete to the best	of my knowledge and belief.	
- 12.			214 / 122
	Yourself TITLE	Area Manager	9/14/83
SIGNED KINEST J. MAN	landin Hire		
7/ 1	$\mathcal{A}$ ,	$A \cap A \cap A$	
VKan	1951 St. 18	Medoust	DATE 2-13-84
APPROVED BY	TITLE	1	