

C/SF

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back (except in case of reservoir).
Use "APPLICATION FOR PERMIT" for such proposals.)

OCT 11 12 50 AM '83

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

WIW - TA

BUR. OF LAND MGMT
ROSWELL DISTRICT

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. BOX 1305 ARTESIA, NEW MEXICO

88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990 FSL & 2310 FEL Sec. 1-18-29

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3515'

NOV 28 1983

O. C. D.

ARTESIA, OFFICE

LC 060905a

6. IF INDIAN, ALIOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

W.L.H. Grb #4 SD UT

8. FARM OR LEASE NAME

Tract 14

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

LOCQ HILLS (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 1-18-29

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

☐
☐
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) P&A

☐
☐
☐

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

7/28/83.....Pulled up 1 jt. and spotted 100 sks cmt w/2% Calcium. WOC. Tagged plug at 2551'. Hole in csg between 1323' and 1449'. Reset pkr at 819'. Using hole in csg. as per Squeezed 100 sks cmt w/2% Calcium. SI 800 psi. WOC.

7/29/83.....Pressured up to 500 psi. Okay. Tagged plug at 1085'. Perforated @ 370' w/4 shots. Squeezed 50 sks cmt w/2% Calcium. SI - no pressure. WOC. Pressured to 500 psi. Held. Tagged plug at 233'. Set 15 sxs cmt - top hole plug. Installed P&A Marker.

Location cleaned, seeded and ready for inspection.

Post ID-2
12-2-83
F&A

18. I hereby certify that the foregoing is true and correct

SIGNED

Ernest J. McLaughlin

TITLE

Area Manager

DATE

9/14/83

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE