

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED IN DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
APR 12 1983

100-511102 (b) 45F
C. IN INDIAN, ALIQUOT OF DEPT. NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WJW - TA
2. NAME OF OPERATOR NEWMONT OIL COMPANY
3. ADDRESS OF OPERATOR

APR 06 1983
O. C. D.
ARTESIA, OFFICE

7. UNIT ACQUISITION NAME
8. FARM OR TRACT NAME
9. WELL NO.
10. FIELD AND POOL, OR WILDCAT
11. SEC., T., R., M., OR BLK. AND
12. COUNTY OR PARISH
13. STATE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
P. O. BOX 1305 ARTESIA, NEW MEXICO 86210
330 FNL 23/0' FEL Sec. 1-18-29

RECEIVED

APR 06 1983

14. PERMIT NO. 3557' 15. ELEVATIONS (Show whether by, for, or to) O. C. D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The above well was plugged and abandoned as follows:

10/28/82.....Spotted 50 sack cement plug at 2855'.

10/29/82.....Tagged plug at 2614'. Spotted 15 sack plug inside casing, loaded hole with mud, pressure tested casing to 600 psi, held. Rigged up wireline and perf base of salt @ 1045', squeezed with 50 sacks cement.

10/30/82....Tagged plug at 920'. Perf top salt @ 459'. Bullhead squeezed 133 sacks, circulated cement to pit.

10/31/82....Tagged at 125', pressured up to 800#, okay. Set 15 sack plug and dry hole marker. Rigged down.

Location ready for inspection.

RECEIVED

MAR 30 1983

Post ID-2
4-15-83
P+H

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

MINERAL SERVICE
ROSWELL, NEW MEXICO
DATE 3/16/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: