

RECEIVED BY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

ARTESIA, NM 88210

Form approved
Budget Bureau No. 42-R1424

6. LEASE DESIGNATION AND SERIAL NO.

LC 051102 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SEP 25 1985 SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

ARTESIA, OFFICE

WELL ☐ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. BOX 1305 ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

330 FNL 2370¹ FEL Sec. 1-18-29

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3557'

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandoned as follows:

10/28/82.....Spotted 50 sack cement plug at 2855'.

10/29/82.....Tagged plug at 2614'. Spotted 15 sack plug inside casing, loaded hole with mud, pressure tested casing to 600 psi, held. Rigged up wireline and perf base of salt @ 1045', squeezed with 50 sacks cement.

10/30/82....Tagged plug at 920'. Perf top salt @ 459'. Bullhead squeezed 133 sacks, circulated cement to pit.

10/31/82....Tagged at 125', pressured up to 800#, okay. Set 15 sack plug and dry hole marker. Rigged down.

Location ready for inspection.

RECEIVED

MAR 30 1983

MINERAL SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: