	SUBSTIT IN TRIPLICY	Form approved. Budget Bureau No. 1004-0135
weight for the states of the states of the states of the state of the		5. LEASE DESIGNATION AND SERIAL NO.
BUREAU OF LAND MANAGEMENArtesia, NM 89210		LC 051102-B
SUNDRY NOTICES AND REPORTS ON (Do not use this form for proposais to drill or to deepen or plug back to Use "APPLICATION FOR PERMIT for such proposal	a different reservoir.	8. IF INDIAN, ALLOTTEE OR TRIBE NAME CIST
WELL WELL OTHER P&A WIW	RECEIVED BY	T. C IT AGREEMENT NAME
2. NAME OF OPERATOR	050 10 1095	8. FALM OR LEASE NAME
Yates Petroleum Corporation V	DEC 12 1985	Ballard B
207 South 4th St., Artesia, NM 88210	Q. C. D.	6
4. LOCATION OF WELL (Report location clearly and in accordance with any State	quiremantESIA, CHICE	10. FELD AND POOL, OR WILDCAT
See also space 17 below.) At surface		Loco Hills-Q-G-SA
2310 FNL & 1650 FEL, Sec. 1-T18S-	D 3 0 E	11. SBC., T., R., M., OR BLE. AND SURVEY OR ARMA
2310 FNL & 1030 FEL, Sec. 1-1185-	-KZ9E	Unit G, Sec. 1-18S-29E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF. RT. G		12. COUNTY OR PARISE 13. STATE
14. PERMIT NO. 3354' KB		Eddy NM
16. Check Appropriate Box To Indicate Nature	of Notice, Report, or C	ther Data
NOTICE OF INTENTION TO:	NOTICE OF INTENTION TO: BUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	WATER SHCT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE	FRACTUBE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON*	SHOOTING OR ACIDIZING	ABANDON MENT"
REPAIR WELL CHANGE PLANS	(Other)	of multiple completion on Well
(Other) (Other	Completion or Recomple	etion Report and Log form.)
 proposed work. If well is directionally drilled, give subsurface locations a nent to this work.)* Propose to plug well as follows: 1. Spot sufficient cement across producing inter shoe. <u>Tag plug</u>. 		
 Isolate Queen formation from overlying zones <u>2235'</u>; top of cement is at <u>1813'</u>. 	with 100' cement	plug. Top of Queen is at
3. Perforate 50' below base of salt at <u>1185'</u> plug in casing. <u>Tag plug</u> .	and squeeze with	50 sx cement, leaving 100'
 4. Perforate 50' above top of salt at <u>355'</u> and plug in casing. <u>Tag plug</u>. 5. Set 30' surface plug and install regulation as a surface plug and install regulation. 	29	
NOTE: 1) NOTIFY BLM, CARLSBAD, NM, (887-6544)	24 HOURS PRIOR TO	BEGINNING WORK.
2) Mud between plugs to be 10#/gallon mud	i-laden fluid.	
18. I hereby certify that the foregoing is true and correct		
SIGNED anita Jos alut TITLE Produce	ction Supervisor	DATE
(This space for Federal or State office use)		
		DATE 12-10 85
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:		JAIB

*See Instructions on Reverse Side