Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

	À	Oiv	ons.	Di	SiO
--	---	-----	------	----	-----

M Ou Ster E

O-28 Anget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

LC-060906

6. If Indian, Allottee or Tribe Name

Use "APPLICATION FO	R PERMIT—" for such proposals (50 10 70)		
SUBMIT	7. If Unit or CA, Agreement Designation		
I. Type of Well X Oil Gas Other	RECEIVED RECEIVED	Mell Name and No.	
2. Name of Operator	REGIRESTA	WLHU G4S Tract #16-1	
YATES PETROLEUM CORPORATION	(505) 748-1470CD ARTESIA	3. API Well No.	
3. Address and Telephone No.		30-015-03247	
105 South 4th St., Artesia,	NM 88210	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey D		Loco Hills-Queen-GB-SA	
660' FNL & 990' FWL of Section	on 1-T18S-R29E (Unit D, NWNW)	Eddy Co., NM	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
Subsequent Report	Plugging Back	Non-Routine Fracturing	
See Story on the see	Casing Repair	Water Shut-Off	
Final Abandonment Notice	Altering Casing	Conversion to Injection	
	X Other Attempt to TA	Dispose Water	
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
	Il pertinent details, and give pertinent dates, including estimated date of star cal depths for all markers and zones pertinent to this work.)*	rting any proposed work. If well is directionally drilled	
11-21-97 - Moved in and rigge	d up pulling unit. Unset pump. Lot	s of drag on 1st and 2nd	
red with 10' out on 3rd red.	Rods are stuck. While working pump	free, got flow of form-	
ation water from tubing. Lea	k in pumping hookup of casing up aro	ound tubinghead and out of	
the ground 3/4" away from wel	1. Worked pump down hole to loosen.	Installed stuffing box	
and secured well as best as p		_	
11-22-97 - Pumped 20 bbls hot	water down tubing. Pump is still s	stuck. Worked rods to tear	
up numn or work loose. POOH	with 68 rods. Nippled up BOP, Laid	l down 49 joints of bad	
2-3/8" tubing Picked up 4-1	1/16" overshot with 5-3/4" OD oversi	zed guide, crossover,	
3-3//" humner sub crossover	and 51 joints of $2-3/8$ " tubing. Tag	ged fish at 1600'. Worked	
to get over fish POOH - no	recovery. Bottom of oversized guide	shows fish is flared	
out so it cannot enter 3-7/8"	ID of overshot bowl. Laid down fis	shing tools. Shut in	
overnight.	Ib of overbilde bourt have bound and		
11_22_24_07 _ TTU with 50 ini	nts of 2-3/8" tubing and laid down s	same. Nippled down BOP.	
Installed 4' sub with valve.		on partner approval to	
plug and abandon.	VOCES	TEPHRASONU	
pad una abanaom	1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	↓ →	

Approved by ______ Title _____ Date ______ Conditions of approval, if any:

Operations Technician