

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYNM 01010105.7
(Other Instru. is on p. 1)
Artesia, NM 88210Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DENIGATION AND SERIAL NO.

LC 060906

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR NEWMONT OIL COMPANY		WEST LOCO HILLS GRB #4 SD	
3. ADDRESS OF OPERATOR P. O. BOX 1305, ARTESIA, NEW MEXICO 88210		8. FARM OR LEASE NAME Tract 16	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' FNL & 330' FWL of Sec. 1		9. WELL NO. 2	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT LOCO HILLS (Q.G.SA)	
15. ELEVATIONS (Show whether F, RT, GR, etc.) 3547' GL		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 1-T18S-R29E	
16. COUNTY OR PARISH Eddy		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) P&A

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/14/83...Tagged bottom, pulled up 1 jt. Mixed 2 sks paper, 2 sks Cottonseed hulls. Followed by 100 sks cement w/25% Calcium. Pulled up 30 stands WOC. 3 hrs. Tagged plug at 2300'. Pulled up 2 stands and mixed mud. Circ. oil out of hole. Pulled tbq.

6/15/83..Ran packer. Hole between 787' and 913'. Pulled packer. Ran wireline and perf @ 1040'. Ran tbq to 1071'. Spotted 50 sks cmt w/2% Calcium. Pulled and set pkr at 693'. Squeezed cmt into perfs. WOC. 4 hrs. Pressure tested plug. No Pressure. Pulled packer. Ran in and tagged plug at 863'. Hole in csg - not covered, spotted 25 sks cmt w/2% Calcium, pulled tbq. Set packer 630'. Squeezed into hole in csg w/200 psi. SI. WOC.

6/16/83...Plug held at 500 psi. Pulled packer. Ran wireline and tagged plug at 790'. Pulled to 470' and perf. w/4 shots. Picked up packer and ran in to 189'. Squeezed 50 sks cmt w/2% Calcium into perfs. SI - no pressure. WOC 4 hrs. Pressured to 500 psi on plug. Plug held. Ran wireline, tagged plug at 353'. Unable to unset packer. Unscrewed from packer and pulled tbq out of hole. Mixed 15 sks cmt. for top hole plug. Installed P&A marker Cleaned location, Seeded and ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

DATE 9/14/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 4/29/87

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Post ID-2
12-2-83
P4A