

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-6058
7. Lease Name or Unit Agreement Name Bassett-Birney State
8. Well No. 5
9. Pool name or Wildcat Loco Hills Q-G-SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) RECEIVED	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Myco Industries Inc	JUN 15 '89
3. Address of Operator 207 South 4th, Artesia, NM 88210	O. C. D. ARTESIA, OFFICE
4. Well Location Unit Letter <u>D</u> : <u>990</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>2</u> Township <u>18s</u> Range <u>29e</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Return to Production</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 2755 PBTD 2742
Pulled tubing and rods cleaned out to PBTD 2742
Treat Metex zone ~~2534-2742~~ w/750 gals 20% NEFE acid
Ran tubing and rods ~~2534-2742~~ and returned to production
6-1-89 pumping 3 BOPD + 52 BW gas TSTM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. A. Gressett TITLE Consultant DATE 6-14-89

TYPE OR PRINT NAME W A Gressett TELEPHONE NO. 748-1471

(This space for State Use)

ORIGINAL SIGNED BY MIKE WILLIAMS

APPROVED BY MIKE WILLIAMS TITLE STATE ENGINEER DATE JUN 23 1989