

COPIES RECEIVED		
CONTRIBUTION		
FE	✓	
SE	✓	✓
U.S.G.S.	2	
LAND OFFICE	✓	
OPERATOR	✓	

RECEIVED BY
OCT 11 1983
O. C. D.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-5524-18

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WIW - <u>TA P&A</u>	7. Unit Agreement Name WEST LOCO HILLS GRB #4
2. Name of Operator NEWMONT OIL COMPANY	8. Farm or Lease Name TRACT 29
3. Address of Operator P. O. BOX 1305 ARTESIA, NEW MEXICO 88210	9. Well No. 2
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>FSL</u> LINE AND <u>2310'</u> FEET FROM THE <u>FWL</u> LINE, SECTION <u>2</u> TOWNSHIP <u>18</u> RANGE <u>29</u> NMPM.	10. Field and Pool, or Wildcat Loco Hills (Q.G.SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3520'	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>P&A</u> <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/21/83..Tagged bottom. Mixed 3 sks paper and spotted 125 sks cmt w/2% CaCl. WOC

6/22/83..Tagged plug at 2362'.
Hole between surface and 63'. Perf w/4 shots at 1000'. Spotted 50 sks cmt w/2% Calcium. Squeezed cmt into perfs. SI w/500 psi. WOC 3 hrs. Plug held at 500 psi. Tagged plug at 906'. Pulled up and perf. at 355'. Bullhead squeezed 50 sks cmt w/2% Calcium. SI 300 psi. WOC.

6/23/83...Pressured to 500 psi. Held. Tagged plug at 242'. Set 15 sk top hole plug, P&A Marker, cleaned Location, seeded and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Emad J. M. Sanay TITLE Area Manager DATE 9/14/83

APPROVED BY Randy Buel TITLE Geologist DATE 2-13-84

CONDITIONS OF APPROVAL, IF ANY: