. OF COPIES RECEIVED	RECEIVED L	Form C-103
		Supersedes Old C–102 and C–103
TAFE NEW MEXICO OIL CONSI	RVATION COMMISSION	Effective 1-1-65
FLE L'I	UUTITIOUS	
U.S.G.S.	O, C, D.	5a. Indicate Type of Lease
LAND OFFICE	ARTESIA, OFFICE	State XX Fee
OPERATOR		5. State Oil & Gas Lease No. B-6846
		b=0040
SUNDRY NOTICES AND REPORTS ON	WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO BEELE A UN FOR SUCH	PROPOSALS.)	7. Unit Agreement Name
	NVX	West Loco Hills Grd #4
2. Nome of Operator	Y41.	8. Farm or Lease Name SD Ut
NEWMONT OIL COMPANY		TRACT 39
3. Address of Operator	· · · · · · · · · · · · · · · · · · ·	9. Well No.
P. O. BOX 1305 ARTESIA, NEW MEXT	CO 88210	1
4. Location of Well	-	10. Field and Pool, or Wildcat
UNIT LETTER O 330 FEET FROM THE	1 2310 1 LINE AND FEET FROM	Loco Hills (Q.G.SA)
East 2 18	RANGENMPM	
15. Elevation (Show whether 3519'	DF, KI, GR, etc.)	12. County Eddy
^{16.} Check Appropriate Box To Indicate N		
NOTICE OF INTENTION TO:	SUBSEQUEN	T REPORT OF:
	· · · · · · · · · · · · · · · · · · ·	ALTERING CASING
PERFORM REMEDIAL WORK	REMEDIAL WORK	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	OTHER P&A	
17. Describe Proposed or Completed Operations (Clearly state all pertinent deto	ils, and give pertinent dates, including	s estimated date of starting any proposed
work) SEE RULE 1103.		
work) SEE RULE 103. 6/16/83 Tagged bottom. Pulled 1 it. Spotted	50 sks cmt w/2% Calciu	
6/16/83Tagged bottom. Pulled 1 jt. Spotted		n. Pulled tbg. S.D.
6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded	hole. Pulled tbg. Se	n. Pulled tbg. S.D. t packer @ 1389'.
6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found	hole. Pulled tbg. Se hole between surface a	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr.
6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl	hole. Pulled tbg. Se hole between surface a nots. Ran tbg to 2509'	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. . Spotted 25 sks cmt.
<pre>6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sh Pulled to 975'. Spotted 50 sks cmt w</pre>	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' 2% Calcium. Pulled tbg	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. . Spotted 25 sks cmt.
6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' 2% Calcium. Pulled tbg	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. . Spotted 25 sks cmt.
6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 si Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi.	hole. Pulled tbg. Se d hole between surface nots. Ran tbg to 2509' 2% Calcium. Pulled tbg SI.	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. . Spotted 25 sks cmt. . Ran packer to 252'.
6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi.	hole. Pulled tbg. Se hole between surface hots. Ran tbg to 2509' 2% Calcium. Pulled tbg 51. e of salt). Pulled tbg	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. . Spotted 25 sks cmt. . Ran packer to 252'. . Tagged plug at 915'.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 	hole. Pulled tbg. Se hole between surface hots. Ran tbg to 2509' 2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotte	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. . Spotted 25 sks cmt. . Ran packer to 252'. . Tagged plug at 915'. d 25 sks cmt. Pulled to
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w, Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Re 460'. Laid down tbg. Spotted 100 sl 	hole. Pulled tbg. Se hole between surface hots. Ran tbg to 2509' 2% Calcium. Pulled tbg 51. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. . Spotted 25 sks cmt. . Ran packer to 252'. . Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed 	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' 2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotte cs cmt w/2% Calcium. P d - no pressure. SI WO	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to alled tbg out of hole. C 4 hrs. Pressure tested
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Re 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug a 	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' 2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179'. Spotted 25 sk	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Re 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug 10aded hole to surface. Laid 	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' 2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179'. Spotted 25 sk	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug a loaded hole to surface. Laid WOC. 	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' 2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179'. Spotted 25 sk d down tbg. Pulled wel	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Ra 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug 10aded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged 	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' 2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179'. Spotted 25 sk d down tbg. Pulled wel	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug a loaded hole to surface. Laid WOC. 	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' 2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179'. Spotted 25 sk d down tbg. Pulled wel	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug a loaded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged Installed P&A Marker. 	hole. Pulled tbg. Se d hole between surface nots. Ran tbg to 2509' /2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179'. Spotted 25 sk d down tbg. Pulled wel d at 45'. Mixed 25 sks for inspection.	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Ra 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug 10aded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged 	hole. Pulled tbg. Se d hole between surface nots. Ran tbg to 2509' /2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179'. Spotted 25 sk d down tbg. Pulled wel d at 45'. Mixed 25 sks for inspection.	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Re 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug 10aded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged Installed P&A Marker. Location cleaned, seeded, and ready 18. I hereby certify that the information above is true and complete to the best of Manual Amale Amale 	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' /2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179". Spotted 25 sk d down tbg. Pulled wel d at 45'. Mixed 25 sks for inspection.	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to alled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Re 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug 10aded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged Installed P&A Marker. Location cleaned, seeded, and ready 18. I hereby certify that the information above is true and complete to the best of Manual Amale Amale 	hole. Pulled tbg. Se d hole between surface nots. Ran tbg to 2509' /2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179'. Spotted 25 sk d down tbg. Pulled wel d at 45'. Mixed 25 sks for inspection.	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to ulled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w, Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug a loaded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged Installed P&A Marker. Location cleaned, seeded, and ready 18. I hereby certify that the information above is true and complete to the best of Market Market And And Market And Market	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' /2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179". Spotted 25 sk d down tbg. Pulled wel d at 45'. Mixed 25 sks for inspection.	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to alled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in. cmt for a top hole plug.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w, Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug a loaded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged Installed P&A Marker. Location cleaned, seeded, and ready 18. I hereby certify that the information above is true and complete to the best of Market Market And And Market And Market	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' /2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179". Spotted 25 sk d down tbg. Pulled wel d at 45'. Mixed 25 sks for inspection.	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to alled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in. cmt for a top hole plug.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w, Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug a loaded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged Installed P&A Marker. Location cleaned, seeded, and ready 18. I hereby certify that the information above is true and complete to the best of Market Market And And Market And Market	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' /2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179". Spotted 25 sk d down tbg. Pulled wel d at 45'. Mixed 25 sks for inspection.	 n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to alled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in.
 6/16/83Tagged bottom. Pulled 1 jt. Spotted 6/17/83Tagged bottom plug at 2509'. Mudded Pressured to 500 psi. Holding. Found Ran wireline and perf. at 975' w/4 sl Pulled to 975'. Spotted 50 sks cmt w, Squeezed cmt into perfs w/300 psi. 6/20/83Pressure up to 500 psi on plug. (Base Pulled to 375'. Perf. w/4 shots. Rate 460'. Laid down tbg. Spotted 100 sl Pulled wellhead and bullhead squeezed plug - would not hold. Tagged plug a loaded hole to surface. Laid WOC. 6/21/83Pressure to 500 psi. on plug. Tagged Installed P&A Marker. Location cleaned, seeded, and ready 18. I hereby certify that the information above is true and complete to the best of Market Market And And Market And Market	hole. Pulled tbg. Se d hole between surface a nots. Ran tbg to 2509' /2% Calcium. Pulled tbg SI. e of salt). Pulled tbg an tbg to 915'. Spotter cs cmt w/2% Calcium. P d - no pressure. SI WO at 179". Spotted 25 sk d down tbg. Pulled wel d at 45'. Mixed 25 sks for inspection.	n. Pulled tbg. S.D. t packer @ 1389'. and 252'. Pulled pkr. Spotted 25 sks cmt. Ran packer to 252'. Tagged plug at 915'. d 25 sks cmt. Pulled to alled tbg out of hole. C 4 hrs. Pressure tested s cmt w/2% CalC which lhead. Closed well in. cmt for a top hole plug.