

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 058480

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WIW	7. UNIT AGREEMENT NAME W. Loco Hills G. 4S. Ut.
2. NAME OF OPERATOR NEWMONT OIL COMPANY ✓	8. FARM OR LEASE NAME Tract 10A
3. ADDRESS OF OPERATOR P. O. BOX 1305, ARTESIA, NEW MEXICO	9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' FNL & 990' FWL of Sec. 3; 18S-29E - NMPM	10. FIELD AND POOL, OR WILDCAT Loco Hills
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3-18S-29E-NMPM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input checked="" type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-18-68 Cleanout to 2590'

7-19-68 Rig up and run Grant notcher and notch at 2580', 2576', 2573', 2569', & 2565'. Check TD at 2590', pick up tubing to 2580' and dump 500 gals 15% reg. acid and displace into formation with plant water.

Put well on injection at 500 BPD rate.

RECEIVED

OCT 9 1968

G. C. C.
ARTESIA, OFFICE

RECEIVED
OCT-8-1968
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Thermon L. Luth*

TITLE Division Superintendent

DATE 9/18/68

(This space for Federal or State office use)

APPROVED BY
COMMISSION OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
OCT 3 - 1968

R. L. BLUMMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side