

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐ WIW - TA

2. NAME OF OPERATOR
NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR
P.O. BOX 1305 ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
2310 FNL 990 FWL Sec. 3-18-29

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3510'

OCT 11 12 52 AM '83
BUR. OF LAND MGMT
ROSWELL DISTRICT

LC 058480

7. UNIT AGREEMENT NAME
West Loco Hills Grb

8. FARM OR LEASE NAME
SD Ut Tract 10A

9. WELL NO.
Well No. 5

10. FIELD AND POOL, OR WILDCAT
Loco Hills (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
3-18-29

12. COUNTY OR PARISH
Eddy

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐ P&A

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8/1/83....Set packer at 2205'. Squeezed 50 sks cement w/2% Calcium Chloride displaced w/16 1/2 bbls water. WOC.

8/2/83....Tagged plug at 2370'. Perforated at 890' w/4 shots/ft. Squeezed sks cement w/2% Calcium. SI 800 psi. WOC. No plug. Spotted 50 cement w/2% Calcium. WOC.

8/3/83....Pressured to 500 psi. Tagged plug at 765'. Perf w/4 shots at 360 Squeezed 50 sks cmt w/2% Calcium - SI - No pressure. WOC. Pressur to 500 psi. Tagged plug at 260'. Mixed 15 sks cmt for top hole p and installed P&A Marker. Location cleaned, seeded and ready for inspection.

Post ID-2
12-2-83
P&A

18. I hereby certify that the foregoing is true and correct

SIGNED Ernest J. McKeen TITLE Area Manager DATE 9/27/83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: