

May 1963

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

OTHER INFORMATION OR NOTES

6. LEASE DENOMINATION AND SERIAL NO.

LC 058480

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

West Loco Hills Grb

8. FARM OR LEASE NAME SD Ut

Tract 10A

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Loco Hills (Q.G.S.A.)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3-18-29

12. COUNTY OR PARISH

Eddy

13. STATE

New Mex

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW - TA

RECEIVED BY

2. NAME OF OPERATOR
Newmont Oil Company ✓

DEC 01 1983

3. ADDRESS OF OPERATOR
P. O. Box 1305, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

330 FSL 1650 FWL Sec. 3-18-29

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3512'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

P&A

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5/12/83...Spotted 100 sks cmt. Tagged plug at 2568'. Spotted additional 100 sacks cmt. WOC.

5/13/83...Tagged plug at 1872'. Hole in csg. between 315' and 378'. Perf 4 sks per ft. at 900'. Spotted 50 sks cmt. Set pkr at 378'. Squeezed cmt WOC. Okay. Tagged plug at 785'. Perf 4 shots/ft. at 370'. Squeezed 50 sks cmt to surface. WOC.

5/14/83...Tagged plug at 265'. Installed 15 sk cmt plug and P&A marker.

Location ready for inspection



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Area Manager

DATE 7/20/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side