

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF

LC 058480

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to an oil or gas reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW - TA

OCT 11 12 53 AM '83

2. NAME OF OPERATOR
Newmont Oil Company

BUR. OF LAND MGMT
ROSWELL DISTRICT

3. ADDRESS OF OPERATOR
P. O. Box 1305 Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

2310' FNL 2310' FWL Sec. 3-18-29

RECEIVED

NOV 28 1983

6. INDIAN, ALLOTTEE OR TRIBE NAME
West Loco Hills Grb #4 SD

8. FARM OR LEASE NAME
Tract 10A

9. WELL NO.
6

10. FIELD AND POOL, OR WILDCAT
Loco Hills (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 3-18-29

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3500'

O. C. D.
ARTESIA, OFFICE

12. COUNTY OR PARISH 13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) P&A

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8/4/83/----Tagged bottom @ 2730'. Spotted 100 sacks cement w/2% calcium @ 2714'. WOC.

8/5/83-----Tagged plug at 2593'. Not enough plug. Mixed 2 sks paper and 2 sks cottonseed hulls followed by 100 sks cmt w/2% CalCl @ 2530'. WOC. Tagged plug at 2236'. Hole between 1000' and 1071'. Held at 300 psi. Perf. w/4 shots/ft. at 900'. Squeezed 50 sks cement at 598'. 500 psi. WOC.

8/6/83-----Plug held at 500 psi. Tagged plug at 750'. Perf. 4 shots/ft. at 390'. Squeezed 50 sks cmt w/2% calcium, SI - no pressure. WOC. Pressure to 500 ..Okay Tagged plug at 273'. Mixed 15 sks cmt for top hole plug. Installed P&A marker

Location cleaned, seeded and ready for inspection.

Post ID-2
12-2-83
P&A

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE Area Manager

DATE 9/9/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: