NO. OF COPIES RECEIVED	44		Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE	1	NEW MEXICO OIL CONSERVATION COMMESSION	<b>C-102 and C-103</b> Effective 1-1-65
FILE	17		
U.S.G.S.		APR 1 9 1971	5a. Indicate Type of Lease
LAND OFFICE			State Fee X
OPERATOR	2.1		5. State Oil & Gas Lease No.
(DO NOT USE THIS FO	SUNDE	Y NOTICES AND REPORTS ON WELLS prosals to drill or to deepen or plug back to a different reservoir. Ion for permit -" (form C-101) for such proposals.)	
1. OIL NUT GAS	<b>—</b> —1		7. Unit Agreement Name
WELL WEL	L L	OTHER- Far	West Loco Hills Sand Unit
2. Name of Operator			8. Farm or Lease Name
	kaa	larko Production Company	Tract No. 8
3. Address of Operator			9. Well No.
	Box	67 Loco Hills, New Mexico 88255	7
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER 0	i	330 FEET FROM THE South LINE AND 1650 FEET FR	Loco Hills
East	LINE. SECTI	0N 4 TOWNSHIP 18 S RANGE 29 E	
		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	//////	3515 GL	Eddy
16.	Check	Appropriate Box To Indicate Nature of Notice, Report or (	Other Data
NOTI			NT REPORT OF:
PERFORM REMEDIAL WORK	7	PLUG AND ABANDON	ALTERING CASING
TEMPORARILY ABANDON	1	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	1	CHANGE PLANS CASING TEST AND CEMENT JOB	
L.	-	OTHER	
OTHER			
17 Describe Proposed or Co	maleted ()	perations (Clearly state all pertipent details and give pertipent dates includ	ing estimated date of starting any proposed

all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled and washed well out to TD 2658 with rotary drilling equipment. The old 7" casing in the well is in poor condition at 1850' and re-completion of this well does not appear advisable. Accordingly, we intend to plug and abandon this well as follows:

Well is presently filled with drilling mud and we will run tubing to approximately 2650' and spot 250 sk. plug of Class H cement w/2% Cacl which will completely fill the hole back into and above the top of the 7" casing stub at 1730'; then pull up and spot 25 sk. plugs at 850' (base of salt), and at 425' (top of salt and base of the 8 5/8" surface casing) and then set a 10 sack plug and surface marker at the surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	$-\rho - \rho$	
	areby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNED D P letton TITLE District Superintendent DATE 15 April 1971		t15 April 1971
APPROVED BY U. a. South TITLE OIL AND GAS INSPECTOR DATE APR 2019	2.1 A GARAGETTAR OU AND GAS INSPECTOR	APR 20 1971

CONDITIONS OF APPROVAL, IF ANY: