

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUN 7 1977

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDY NOTICES AND REPORTS ON WELLS</p> <p>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease</p> <p>State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. Name of Operator Anadarko Production Company</p> <p>3. Address of Operator P. O. Box 67, Loco Hills, New Mexico 88255</p> <p>4. Location of Well</p> <p>UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 18S RANGE 29E N.M.P.M.</p> <p>15. Elevation (Show whether DF, RT, GR, etc.) 3590</p>		<p>7. Unit Agreement Name Ballard Grayburg</p> <p>8. Farm or Lease Name San Andres Unit</p> <p>9. Well No. 1</p> <p>10. Field and Pool, or Wildcat Loco Hills Queen</p> <p>11. Grayburg San Andres</p> <p>12. County Eddy</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit, pull rods and tubing.
2. Wash out to T. D.
3. Drill additional Grayburg from 2688 to 2750.
4. Return well to production

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by Jerry E. Buckles	TITLE Area Supervisor	DATE June 6, 1977
APPROVED BY W. A. Gressett	TITLE SUPERVISOR, DISTRICT II	DATE JUN 7 1977

CONDITIONS OF APPROVAL, IF ANY: