

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WATER INJECTION WELL	WELL API NO. 30-015-03308
2. Name of Operator Anadarko Petroleum Corp.	5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
3. Address of Operator P.O. Box 2497 Midland, TX 79702	6. State Oil & Gas Lease No. N/A
4. Well Location Unit Letter <u>E</u> : <u>1980</u> feet from the <u>NORTH</u> line and <u>660</u> feet from the <u>WEST</u> line Section <u>5</u> Township <u>18S</u> Range <u>29E</u> NMPM County <u>EDDY</u>	7. Lease Name or Unit Agreement Name: BALLARD GRAYBURG SAN ANDRES UNIT TRACT 10
10. Elevation (Show whether DR, RKB, RT, GR, etc.) N/A	8. Well No. 1
	9. Pool name or Wildcat LOCO HILLS ON GB SA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRUPU. KILL WELL. NDWH. NU & TEST BOPE. RLSE PKR & POOH W/TBG.
2. RIH W/TBG TO 2880'. CIRC HOLE W/MUD.
3. SET CIBP @ 2550'. SPOT 25 SX CL C CMT ON PLUG. WOC. TAG PLUG.
4. PERFORATE CSG @ 825'. SET CR @ 675'. STING INTO CR & EST RATE. PUMP 100 SX CL C. STING OUT OF CR & DUMP 10 SX CL C ON PLUG. (BASE OF SALT)
5. PERFORATE CSG @ 360'. EST CIRC. PUMP 100 SX CL C AND CIRC TO SURF. TAG CMT.
6. PUMP 10 SX SURFACE PLUG. CUT OFF & INSTALL P&A MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE SABRA WOODY TITLE ENGR TECH III DATE 03/02/01

Type or print name SABRA WOODY Telephone No. 915/683-0534

(This space for State use)

APPROVED BY Record Only TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any: \_\_\_\_\_

# Ballard Unit Tr.10 #1 (formerly Miller Fed. #1)

Grayburg/San Andres

1980' FNL & 660' FWL, Sec. 5, T18S, R29E, Eddy County, New Mexico

Spudded 12/9/1963

