

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI. DATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-061701

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Convert for water injection.**2. NAME OF OPERATOR
Anadarko Production Company ✓3. ADDRESS OF OPERATOR
P. O. Box 67, Loco Hills, New Mexico 882554. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface**990' FSL & 990' FWL**

OCT 19 1973

RECEIVED

7. UNIT AGREEMENT NAME

**Ballard Grayburg
San Andres Unit**

8. FARM OR LEASE NAME

Tract No. 14

9. WELL NO.

**3
Loco Hills Grayburg
San Andres**11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**8 - 183 - 290 E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Not Available **O. C. C.**
ARTESIA, OFFICE

12. COUNTY OR PARISH

Eddy

13. STATE

N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. Rig up well servicing unit. Pull tubing and rods.
2. Clean out to T. D. 3036'.
3. Run Gamma Ray-Compensated Neutron Log.
4. Test top of 5½" liner for leakage.
5. Run 2 3/8" plastic lined tubing. Set packer in 5½" casing from 2200'-2910'.
6. Equip well for water injection into Jackson zone of San Andres.
7. Place well on injection in accordance with N. M. O. C. C. Order R-4493.

18. I hereby certify that the foregoing is true and correct

SIGNED

M. F. Nelson

TITLE

Area Supervisor

DATE

Oct. 15, 1973

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
OCT 16 1973
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICOAPPROVED
OCT 18 1973
R. L. BECKMAN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations of Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.