

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-050906

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT DESIGNATION NAME
Bailly, Grayburg
San Andres Unit

8. FARM OR LEASE NAME

Tract No. 5

9. WELL NO.

3

10. FIELD AND ZONE, OR WHEREAT
Loce Hills Grayburg
San Andres11. SEC., T., R., S., OR BLK. AND
SURVEY OR AREA

8 - 18S - 29E

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

1. OIL ☐ WELL GAS ☐ WELL OTHER ☒ convert for water injection

2. NAME OF OPERATOR

Anadarko Production Company ✓

3. ADDRESS OF OPERATOR

P. O. Box 67, Loce Hills, New Mexico, 88255

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

330' FSL & 2310' FeL

OCT 19 1973

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Not Available

O. C. C.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for markers and zones pertinent to this work.)*

1. Rig up well servicing unit. Pull tubing and rods.
2. Clean out to T. D. 3040'.
3. Log with Gamma Ray-Compensated Neutron Log.
4. Deepen into the Jackson section of the San Andres if necessary.
5. Run 2450' of 4 1/2" 10.50# K-55 casing.
6. Tie onto top of 5" casing at 2450'.
7. Cement with enough cement to bring cement up into the 7" casing.
8. Run plastic lined 2 3/8" tubing with a packer.
9. Equip for water injection into the Jackson Zone of the San Andres.
10. Place well on injection in accordance with N. M. O. C. C. Order R-4493.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supervisor

DATE

October 11, 1973

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations. Any approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions, to complete the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, location of Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of a abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing; and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.