

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
RECEIVED

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUL 23 1976

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name Far West Loco Hills Sand Unit	
8. Farm or Lease Name Tract No. 9	
9. Well No. 10	
10. Field and Pool, or Wildcat Loco Hills	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELL O. C. C.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Water Injection Well		7. Unit Agreement Name Far West Loco Hills Sand Unit	
2. Name of Operator Anadarko Production Company		8. Farm or Lease Name Tract No. 9	
3. Address of Operator P. O. Box 67, Loco Hills, New Mexico 88255		9. Well No. 10	
4. Location of Well UNIT LETTER C 330 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 18S RANGE 29E NMPM.		10. Field and Pool, or Wildcat Loco Hills	
15. Elevation (Show whether DF, RT, GR, etc.) 3506 GL		12. County Eddy	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pump Halliburton Injectrol G down 2-3/8" Injection tubing, wait approximately 48 hours.
2. Rig up pulling unit, unset injection paker, pull tubing.
3. Sand drill Loco Hills zone in open hole from 2446' to 2470'.
4. Clean out sand to 2495'.
5. Run 2-3/8" plastic lined tubing.
6. Load annulus with fresh water and chemical.
7. Resume water injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed by Jerry E. Buckles TITLE Area Supervisor DATE July 22, 1976

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUL 26 1976

CONDITIONS OF APPROVAL, IF ANY: