

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

MAR 10 1976

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

B. C. C.

ARTESIA, OFFICE

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Water Injection Well</b>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator <b>Anadarko Production Company</b>	5. State Oil & Gas Lease No.
3. Address of Operator <b>P. O. Box 67, Loco Hills, New Mexico 88255</b>	7. Unit Agreement Name <b>Ballard Grayburg San Andres Unit</b>
4. Location of Well UNIT LETTER <b>D</b> <b>330</b> FEET FROM THE <b>West</b> LINE AND <b>990</b> FEET FROM THE <b>North</b> LINE, SECTION <b>9</b> TOWNSHIP <b>18S</b> RANGE <b>29E</b> NMPM.	8. Farm or Lease Name <b>Tract No. 22</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>Not available</b>	9. Well No. <b>4</b>
	10. Field and Pool, or Wildcat <b>Loco Hills Queen Grayburg San Andres</b>
	12. County <b>Eddy</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Convert for water injection</b>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit, about 4-15-76, pull rods and tubing.
2. Clean out to T. D. 2652. Drill approximately 100' of new hole.
3. Run Gamma Ray Neutron Logs.
4. Perforate additional Grayburg zones and acidize.
5. Run injection packer on 2-3/8" plastic lined tubing.
6. Load annulus with fresh water and chemical.
7. Set packer.
8. Commence water injection, about 5-1-76, in accordance with N. M. O. C. C. Order R-4493.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by  
**Jerry E. Buckles**

SIGNED

TITLE **Area Supervisor**

DATE **March 8, 1976**

APPROVED BY **W. A. Gressett**

TITLE **SUPERVISOR, DISTRICT II**

DATE **MAR 11 1976**

CONDITIONS OF APPROVAL, IF ANY: